

FIELD PHOTOGRAPHY LOG SHEET

D.5  
3/27/91

SITE NAME: PLYMOUTH CENTER SITE

PAGE 1 OF 6

U.S. EPA ID: MID98558633

TDD: F05-9102-029

PAN: FMT 1233PA

DATE: 3-27-91

TIME: 9:35 AM

DIRECTION OF  
PHOTOGRAPH:

N

WEATHER  
CONDITIONS:

OVERCAST

45°F

PHOTOGRAPHED BY:

CONNERT

SAMPLE ID  
(if applicable):

DESCRIPTION:

SUSPECTED BOILER BUILDING

US EPA RECORDS CENTER REGION 5



530279

933408

DATE: 3-27-91

TIME: 9:44

DIRECTION OF  
PHOTOGRAPH:

S

WEATHER  
CONDITIONS:

OVERCAST

45°F

PHOTOGRAPHED BY:

CONNERT

SAMPLE ID  
(if applicable):

DESCRIPTION:

SOUTH SIDE OF SUSPECTED BOILER BUILDING





FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: PLYMOUTH CENTER SITE

PAGE 2 OF 6

U.S. EPA ID: AND 9855 86833

TDD: FOS-9102-029

PAN: EMI 1733PA

DATE: 3-27-91

TIME: 957

DIRECTION OF  
PHOTOGRAPH:

SE

WEATHER  
CONDITIONS:

OVERCAST

45°F

PHOTOGRAPHED BY:

CONNETT

SAMPLE ID  
(if applicable):



DESCRIPTION: NW AREA OF SUSPECTED BOILER BUILDING

DATE: 3-27

TIME: 10:10

DIRECTION OF  
PHOTOGRAPH:

SW

WEATHER  
CONDITIONS:

OVERCAST

45°F

PHOTOGRAPHED BY:

CONNETT

SAMPLE ID  
(if applicable):



DESCRIPTION: SUSPECTED BOILER BUILDING



FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: PLYMOUTH CENTER SITE

PAGE 3 OF 6

U.S. EPA ID: MID9855 86833

TDD: F05-9102-029

PAN: FMI1233RA

DATE: 3/27/91

TIME: 930am

DIRECTION OF  
PHOTOGRAPH:

NF

WEATHER  
CONDITIONS:

OVERCAST

45°F

PHOTOGRAPHED BY:

COWNETT

SAMPLE ID  
(if applicable):



DESCRIPTION: UNIDENTIFIED ROUND CIRCULAR BUILDING EAST OF BOILER BUILDING

DATE: 3/27/91

TIME: 947am

DIRECTION OF  
PHOTOGRAPH:

E

WEATHER  
CONDITIONS:

OVERCAST

45°F

PHOTOGRAPHED BY:

COWNETT

SAMPLE ID  
(if applicable):



DESCRIPTION: OPEN MANHOLE COVER NORTHWEST OF SUSPECTED BOILER BUILDING



FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: PLYMOUTH CENTER SITE

PAGE 4 OF 6

U.S. EPA ID: MID985586833

TDD: F05-9102-029

PAN: FM1-1233PA

DATE: 3-27-91

TIME: 937 AM

DIRECTION OF  
PHOTOGRAPH:

W

WEATHER  
CONDITIONS:

OVERCAST

45°F

PHOTOGRAPHED BY:

CONNETT

SAMPLE ID  
(if applicable):

DESCRIPTION:

GARAGE BUILDING NEXT TO SUSPECTED BOILER HOUSE



DATE: 3-27-91

TIME: 1015

DIRECTION OF  
PHOTOGRAPH:

S

WEATHER  
CONDITIONS:

OVERCAST

45°F

PHOTOGRAPHED BY:

CONNETT

SAMPLE ID  
(if applicable):

DESCRIPTION:

ABANDONED BUILDING: ALFRED BINET HALL





FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: PLYMOUTH CENTER SITE

PAGE 5 OF 6

U.S. EPA ID: M10985586833

TDD: F05-9102-029

PAN: FMI1233 PA

DATE: 3-27-91

TIME: 11:20

DIRECTION OF  
PHOTOGRAPH:

NW

WEATHER  
CONDITIONS:

OVERCAST

45°F

PHOTOGRAPHED BY:

CONNERT

SAMPLE ID  
(if applicable):

DESCRIPTION:

SUSPECTED SECURITY BUILDING W/



DATE: 3-27-91

TIME: 11:22

DIRECTION OF  
PHOTOGRAPH:

N

WEATHER  
CONDITIONS:

OVERCAST

45°F

PHOTOGRAPHED BY:

CONNERT

SAMPLE ID  
(if applicable):

DESCRIPTION:

CLOSE UP OF DISCHARGE PIPE POSSIBLY FROM SUSPECTED SECURITY BUILDING





FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: PLYMOUTH CENTER SITE

PAGE 6 OF 6

U.S. EPA ID: MID985586833

TDD: F05-9102-029

PAN: FMI1233

DATE: 3-27-91

TIME: 9:44 AM

DIRECTION OF  
PHOTOGRAPH: E

WEATHER  
CONDITIONS:

OVERCAST

45° F

PHOTOGRAPHED BY:

CONNETT

SAMPLE ID  
(if applicable):

DESCRIPTION:

INTERMITTENT CREEK FLOWING EAST FROM SITE



DATE: 3-27-91

TIME: 9:45 AM

DIRECTION OF  
PHOTOGRAPH: S

WEATHER

CONDITIONS: OVERCAST 45°F

PHOTOGRAPHED BY: CONNETT

SAMPLE ID  
(if applicable):

DESCRIPTION: INTERMITTENT

CREEK FLOWING EAST FROM

SUSPECTED BOILER BUILDING IN

BACKGROUND

























































NON-RESPONSIVE



NON-RESPONSIVE

















































